

BELZONA REPLACES NON-SLIP TAPES ON RAMP

ID: 2479



PROBLEM

The ramp was a potential slip hazard and adhesive tapes had been unsuccessfully used to create a non-slip surface. A more positive, long term solution was required.

APPLICATION SITUATION

Ramp made of travertine stone.

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet FPA-8.

BELZONA FACTS

After the application, the ramp is as new and safe for pedestrians. This application is reported to still be in perfect condition in 2012.

INDUSTRY

Buildings & Structures

LOCATION

Hospital, France

APPLICATION DATE

February 2003

PRODUCTS

Belzona 4411 (Granogrip)

SUBSTRATE

Travertine stone

PHOTOS

1. Ramp with failed tape system clearly evident
2. Ramp after application of Belzona 4411
3. Close view of the application
4. General view of the ramp at the hospital entrance

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

