

BELZONA ANCHORS NEW RUDDER BUSHES IN POSITION

ID: 253

PROBLEM

The original bushes were bronze and had caused galvanic corrosion of the housing within one year, becoming loose.

APPLICATION SITUATION

Becker flap rudder slider bearings.

APPLICATION METHOD

The application was carried out in accordance with a modified version of Belzona Know-How System Leaflet SOS-9. Belzona®1321 functions as structural adhesive, support, and coating in this application.

BELZONA FACTS

This method significantly reduced the installation time and cost for bearing replacement, and extended the lifetime of the component, by eliminating future galvanic, crevice, or general corrosion from this part of the rudder. Four rudders were repaired in less than a week and Belzona is used from new to prevent these problems.

INDUSTRY

Marine

LOCATION

Shipping - International car transporter

APPLICATION DATE

April 2000

PRODUCTS

Belzona 1321 (Ceramic S-Metal)

SUBSTRATE

Synthetic bearing and steel

PHOTOS

1. Condition of corroded housing before repair
2. Installation of the synthetic bearing, using Belzona 1321 as both adhesive and coating and "screwing" bearing into the housing
3. Completed repair
4. Location of the slider on top of the rudder flap

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

