

BELZONA HELPS KEEP THIS POWER PLANT ON-LINE

ID: 257



PROBLEM

A bearing seizure damaged the armature shaft in fuel generator.

APPLICATION SITUATION

Damaged armature shaft.

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet MPT-2.

BELZONA FACTS

Belzonas famous in place split former repair used less than \$50 worth of material and saved this company thousands of dollars in repair costs and downtime.

INDUSTRY

Power

LOCATION

Power plant in eastern Kansas, U.S.A.

APPLICATION DATE

Winter 2000

PRODUCTS

Belzona 1111 (Super Metal)

SUBSTRATE

Steel

PHOTOS

1. Surface preparation
2. The former is being tightened
3. The former is removed

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

