

BELZONA KEEPS THE TRAFFIC MOVING: FOUR YEARS AND GOING STRONG

ID: 262



PROBLEM

Continuous impact from traffic damaged the outer concrete ring seat causing problems. The traffic could not be disrupted for an extended period of time.

APPLICATION SITUATION

Valve well cover ring seat, located on a busy road.

APPLICATION METHOD

The application was carried out in accordance with a modified version of Belzona Know-How System Leaflet GSS-7.

BELZONA FACTS

The Belzona solution allowed the city to reset the valve well and manhole covers before further damage occurred, with the least amount of material and traffic disruption.

INDUSTRY

General Industry

LOCATION

Local municipality in British Columbia, Canada

APPLICATION DATE

March 1997

PRODUCTS

Belzona 1211 (E-Metal)

SUBSTRATE

Concrete and Steel

PHOTOS

1. Close look at the damage prior to Belzona repair
2. Completed job, still in service after four years

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

