


BELZONA 5811 REPEAT TANK APPLICATION

ID: 264



PROBLEM

Corrosion under base of original tank necessitated fabrication and protection of new tank.

APPLICATION SITUATION

Tank used to retrieve lost raw material from ventilation system.
Contains sea water and alum earth.

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet TCC-5. After stripe coating welds, brackets and other awkward areas. The Belzona® 5811 was applied by heated airless spray.

BELZONA FACTS

Belzona® 5811 originally applied to tank in 1993 was still in excellent condition. However, the tank had corroded on the outside between base and concrete so a new tank had to be fabricated. The client had no hesitation in specifying Belzona® 5811 again.

INDUSTRY

General Industry

LOCATION

Aluminium producer in Holland

APPLICATION DATE

1993 and February 2001

PRODUCTS

Belzona 5811 (Immersion Grade)
Belzona 5981

SUBSTRATE

Steel

PHOTOS

1. The first coat of Belzona 5811 (beige) applied and details being stripe coated
2. Second coat of Belzona 5811 (black) applied
3. Tank re-installed in original position

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

