

BELZONA RESTORES FELT RETURN ROLL

ID: 268



PROBLEM

The fiberglass roll coating had worn to such an extent that the fibrous reinforcement was protruding from the surface of the coating, allowing water to ingress into the coating.

APPLICATION SITUATION

Felt return roll.

APPLICATION METHOD

The application was carried out in accordance with a modified version of Belzona Know-How System Leaflet SHM-12.

BELZONA FACTS

Belzona® 1321 was easily applied on site, leading to a quick turnaround time which was reduced the cost of the application. Due to the greater abrasion resistance of the Belzona® 1321 over fiberglass, the Belzona System has considerably extended the life of the roll.

INDUSTRY

Pulp & Paper

LOCATION

Paper mill in the south of England

APPLICATION DATE

April 2001

PRODUCTS

Belzona 1321 (Ceramic S-Metal)

SUBSTRATE

Fibrous reinforcement sheet

PHOTOS

1. Previous coating showing signs of wear
2. Applying Belzona 1321
3. The roll in service on the paper machine

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

