


# LIVE LEAK SEALING WITH BELZONA

ID: 2691



## PROBLEM

The pipe which carried the cool water to the primary mill was leaking. The engineers were looking to repair the pipe with minimal downtime but so far had not yet been able to come up with a method for how they would do this.

## APPLICATION SITUATION

Leaking cooling water pipe.

## APPLICATION METHOD

Application was carried out in accordance to Belzona Know-How System Leaflet VPF-11. Temporary seal effected with Belzona® 1291 before reinforcing with Belzona 1161 to create more permanent seal.

## BELZONA FACTS

To shut down the pipe line for a traditional repair could cost the company up to £60,000 per hour. Belzona were able to offer a very cost effective live leak repair. The repair, visited 3 years on was showing no sign of deterioration.

## INDUSTRY

Heating, Ventilation & Air Conditioning

## LOCATION

Leeds, UK

## APPLICATION DATE

February 2008

## PRODUCTS

Belzona 1291 (ES-Metal)

Belzona 1161 (Super UW-Metal)

## SUBSTRATE

Steel pipe

## PHOTOS

1. Severe leak
2. Leak plugged with Belzona 1291
3. Attention to detail during application of Belzona 1161
4. Finished application

For more examples of Belzona Know-How in Action, please visit [khia.belzona.com](http://khia.belzona.com)

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

[www.belzona.com](http://www.belzona.com)

