

BELZONA PROTECTS FLARE DRUM

ID: 2740



PROBLEM

Vessel suffering internal corrosion. Coating required to extend service life of the vessel.

APPLICATION SITUATION

Flare knock-out drum

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet TCC-5.

BELZONA FACTS

Belzona® 1391 provides excellent corrosion protection at elevated temperatures. In particular the coating is capable of withstanding the extreme variations in temperature and pressure the vessel is exposed to. The ambient temperature curing coating lends itself to application on-site.

INDUSTRY

Chemical & Petrochemical

LOCATION

Refinery, UK

APPLICATION DATE

November 2011

PRODUCTS

Belzona 1391 (Ceramic HT)

SUBSTRATE

Carbon Steel

PHOTOS

1, 2 & 3. various views of the Belzona 1391 applied to the vessel interior.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com



Copyright © 1952-2026 Belzona International Limited.