

BELZONA MAKES FUELING AREAS SAFER

ID: 276



PROBLEM

Bus refueling station had several workman's compensation claims from employees slipping at pump areas.

APPLICATION SITUATION

Fuel pump area

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet FPA-8.

BELZONA FACTS

Belzona® 4411 had already proven to be durable and effective in a heavy traffic area at the bus garage. This application at the refueling station relieved the demands from the workman's compensation authorities, who mandated that the pump area be made more safe or that they hire attendants who are exempt from workman's compensation.

INDUSTRY

General Industry

LOCATION

St Lucie County, Florida Schools - Maintenance Dept.

APPLICATION DATE

January 2002

PRODUCTS

Belzona 4411 (Granogrip)

SUBSTRATE

Painted concrete

PHOTOS

1. An overview of the pump station
2. A pump prior to the application
3. Spills can be seen where the non-skid system has been applied
4. A close up of the completed application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

