

BELZONA RESTORES LOCAL BANK

ID: 2776



PROBLEM

Age and the effect of weather had caused serious deterioration to the buildings facade.

APPLICATION SITUATION

Window sills, lintels and the external walls of the bank.

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflets WPA-1 and WPA-4. The defective external wall coatings were removed. Some of the broken profiles around the windows and the lintel above the front door were repaired with Belzona® 4141. Belzona® 5151 was then applied to the stonework to protect the surface from further damage.

BELZONA FACTS

The poor appearance of the bank led to the village being rejected for a Civic Trust award. This led to pressure on the bank to improve its external facade. The Belzona solution was chosen for its speed in carrying out the upgrade and the self-cleaning properties of the Belzona® 5151 will ensure the buildings appearance will be maintained for many years to come.

INDUSTRY

Buildings & Structures

LOCATION

Bank, Scotland

APPLICATION DATE

March 2011

PRODUCTS

Belzona 4141 (Magma-Build)

Belzona 5151 (Hi-Build Cladding)

SUBSTRATE

Stone

PHOTOS

1. Fascia of the building prior to application
2. Damaged Column
3. General view of the completed application
4. The refurbished bank entrance

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

