

BELZONA LOW ODOUR SOLUTION FOR TRAINING COLLEGE ROOF

ID: 2825



PROBLEM

The Estates office of the College had a number of reports that water was entering the building. The roof leak was creating health and safety issues within the building.

APPLICATION SITUATION

Roof over Police Training College.

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet RPA-8. Damage in the asphalt was repaired with Belzona® 4111 before the complete roof was sealed with a fully reinforced Belzona® 3111 System.

BELZONA FACTS

The college required a solution that would not disturb the students studying in the classrooms below. The water based Belzona 3111 is low odour and surface cleaning and application did not create any disturbing noise allowing the college to function without interruption.

INDUSTRY

Buildings & Structures

LOCATION

Police Training College, South East England

APPLICATION DATE

July 2010

PRODUCTS

Belzona 4111 (Magma Quartz)
Belzona 3111 (Flexible Membrane)

SUBSTRATE

Asphalt

PHOTOS

1. The roof being washed down ready for the repairs and coating
2. Preparation completed and the Conditioner being applied
3. First and second coats of Belzona 3111 completed
4. Completed application of Belzona 3111 system

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

