

BELZONA NON-SKID SYSTEM REMOVES SLIP AND FALL HAZARD

ID: 289



PROBLEM

The floor was plagued with constant complaints arising from slippery floor tiles. Non-skid tape safety pads were in use in strategic areas, but were constantly delaminating from the wet environment and harsh cleaning chemicals.

APPLICATION SITUATION

Quarry tiled floor in a hospital dish washing area.

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet FPA-8.

BELZONA FACTS

It was found that the Belzona system initially cost about 30% more, but eliminated the need for replacement pads. The application has been in service for 5 years with no required maintenance.

INDUSTRY

General Industry

LOCATION

Hospital in British Columbia, Canada

APPLICATION DATE

1997

PRODUCTS

Belzona 1321 (Ceramic S- Metal)

Belzona 9221 (Surefoot Aggregate)

SUBSTRATE

Quarry Tile

PHOTOS

1. Surface preparation with template
2. Glaze removed from quarry tile floor
3. Masking tape removed after the application is complete
4. Completed application of grip system

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

