

BELZONA FOR THE REPAIR OF STEP NOSINGS

ID: 290



PROBLEM

The step nosings leading to a loading area became rounded from constant traffic and improper handtruck usage.

APPLICATION SITUATION

Steps at a furniture manufacturing facility leading to a loading area.

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet FPA-8.

BELZONA FACTS

The leading edges of steps take a tremendous beating, and the Belzona material has a combination of adhesive as well as the compressive strength in order to provide a long lasting solution.

INDUSTRY

Buildings & Structures

LOCATION

Furniture manufacturer in North Carolina U.S.A.

APPLICATION DATE

May 2000

PRODUCTS

Belzona 4111 (Magma Quartz)
Belzona 4411 (Granogrip)

SUBSTRATE

Concrete

PHOTOS

1. Damage to step nosings
2. Belzona 4911 (TX Conditioner) applied to steps
3. Peeling tape off to reveal Belzona 4411 (Granogrip)
4. Completed application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

