

BELZONA KEEPS ENTRANCE WAY STEPS LOOKING GOOD AND SAFE

ID: 292



PROBLEM

Various non-skid materials had previously been applied to the nosings of these quarry tile steps with no long-term success.

APPLICATION SITUATION

Step nosings along a very visible entrance way.

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet FPA-8.

BELZONA FACTS

Belzona® 4411 (Granogrip) was applied by brush in conjunction with Belzona® 9221 (Surefoot Aggregate) on the nosings of the quarry tile steps. 1/4 inch tape was cut and placed over the grout lines of the tile to simulate the quarry tile appearance. This area is high visibility for visiting dignitaries and tourists, so emphasis was placed on safety and cosmetics.

INDUSTRY

Buildings & Structures

LOCATION

Agency building - Houston, Texas U.S.A.

APPLICATION DATE

April 1985

PRODUCTS

Belzona 4411 (Granogrip)

Belzona 9221 (Surefoot Aggregate)

SUBSTRATE

Quarry Tile

PHOTOS

1. Pulling the tape while the Belzona 4411 is still wet
2. View of entire area
3. Close-up view of completed application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

