




# BELZONA SUCCESSFULLY REFURBISHES SCHOOL STEPS

ID: 2928



## PROBLEM

Steps were leaking into a wash room below so needed to be sealed. Also access to the roof was needed so slip hazards had become an issue.

## APPLICATION SITUATION

Steps over wash room in school

## APPLICATION METHOD

Application was carried out in accordance with Belzona Know How System Leaflet FPA-8

## BELZONA FACTS

Repairs were carried out over two days and have now provided the school with waterproof and safe steps. They were so pleased with the results that they had other sets of steps coated with Belzona 4411.

## INDUSTRY

Buildings & Structures

## LOCATION

Warwickshire, UK

## APPLICATION DATE

May 2011

## PRODUCTS

Belzona 5811 (Immersion Grade)  
Belzona 4411 (Granogrip)

## SUBSTRATE

Concrete

## PHOTOS

1. Application of Belzona 5811 to walls.
2. Application of Belzona 5811 to steps.
3. Complete encapsulation of steps and walls.
4. Completed application with Belzona 4411 on step noses.

For more examples of Belzona Know-How in Action, please visit [khia.belzona.com](http://khia.belzona.com)

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

[www.belzona.com](http://www.belzona.com)

