


BELZONA REFURBISHES SCHOOL STEPS

ID: 2929



PROBLEM

Steps were allowing water into the wash room below so needed to be sealed. Also access to the roof was needed so elimination of any slip hazards had become an issue.

APPLICATION SITUATION

Access steps to roof of school with wash room underneath.

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet FPA-8

BELZONA FACTS

Repairs were carried out over two days and have now provided the school with safe and waterproof steps. Following the success of this repair, the customer has since treated several other steps on the site with Belzona 4411.

INDUSTRY

Buildings & Structures

LOCATION

Warwickshire, UK

APPLICATION DATE

May 2011

PRODUCTS

Belzona 5811 (Immersion Grade)
Belzona 4411 (Granogrip)

SUBSTRATE

Concrete

PHOTOS

1. Application of Belzona 5811 to walls
2. Application of Belzona 5811 to steps
3. Complete encapsulation of steps and wall
4. Completed application with Belzona 4411 on step noses

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

