

BELZONA REPAIRS DAMAGED FLOOR AT CIDER PLANT

ID: 2931



PROBLEM

Due to spillage of cider concentrate the concrete floor had begun to break up and created health and safety issues with trips and slips.

APPLICATION SITUATION

Inspection hut floor in cider storage tank area

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet FPA-1. Belzona® 4131 used to repair damaged concrete and level surface before coating with Belzona 5231.

BELZONA FACTS

Both Belzona® 4131 and Belzona® 5231 have been used many times around the site to protect against the effects of the cider. Alternatives have been tried before but Belzona offers them the best long term solution. The Belzona system used enabled floor to be levelled and then finished with slip resistant hygienic surface.

INDUSTRY

General Industry

LOCATION

Cider producer, Herefordshire, UK

APPLICATION DATE

January 2012

PRODUCTS

Belzona 4131 (Magma Screed)
Belzona 5231 (SG Laminate)

SUBSTRATE

Concrete

PHOTOS

1. Damaged floor
2. Application of Belzona 4131 including conditioner to ensure maximum adhesion
3. Complete floor repaired with Belzona 4131
4. Application of Belzona 5231 completed

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com


BELZONA®

Copyright © 1952-2026 Belzona International Limited.