


BELZONA MAKES WALKWAY SAFE

ID: 2953



PROBLEM

Delamination of resin floor had caused a trip hazard. When the repair was looked at they noted that there was a slip hazard in the same area.

APPLICATION SITUATION

Walkway in production area of Cider Plant

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet FPA-8. Belzona® 4131 applied to level floor area before applying Belzona® 4411 grip system.

BELZONA FACTS

When routine maintenance was carried out they would step out of a small bund with wet feet. Belzona® 4131 ability to be feather edged allowed easy levelling of the walkway. The yellow Belzona® 4411 was chosen as both a positive grip system and as a visual aid.

INDUSTRY

General Industry

LOCATION

Cider producer, Herefordshire, UK

APPLICATION DATE

September 2011

PRODUCTS

Belzona 4131 (Magma Screed)
Belzona 4411 (Granogrip)

SUBSTRATE

Concrete

PHOTOS

1. Trip hazard levelled with Belzona 4131
2. Application of Belzona 4411
3. Removal of masking tape
4. Completed application.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

