

BELZONA REPAIRS DAMAGED CONCRETE AT CIDER PLANT

ID: 2955



PROBLEM

Damaged concrete on walkway was identified as a trip hazard.

APPLICATION SITUATION

Pedestrian crossing at cider plant

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet FPA-5 & 6. Damaged joint nosings were reformed with Belzona® 4131 before sealing joint with Belzona® 2211.

BELZONA FACTS

Other cheaper products had been used to try and fix problem but with no success. Belzona was chosen due to its proven reliability and longevity at other applications around the site. Belzona 4131 provides an impact resistant joint nosing whilst Belzona® 2211 provides strongly bonded highly elastic joint sealant.

INDUSTRY

General Industry

LOCATION

Cider producer, Herefordshire, UK

APPLICATION DATE

August 2011

PRODUCTS

Belzona 4131 (Magma-Screed) Belzona 2211 (MP Hi-Build Elastomer)

SUBSTRATE

Concrete

PHOTOS

Previous attempted repair Nosings rebuilt with Belzona 4131 Application of Belzona Elastomer Conditioner Completed application with joint sealed using Belzona 2211

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com



Copyright © 1952-2026 Belzona International Limited.