

BELZONA HEALS HOSPITAL EXPANSION JOINTS

ID: 297



PROBLEM

Deteriorated expansion joints cause problems with x-ray equipment as well as with individuals tripping throughout the hallways.

APPLICATION SITUATION

Deteriorated expansion joints throughout hospital hallways.

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflets FPA-5 and FPA-6.

BELZONA FACTS

In all, seven joints have been refurbished using this Belzona System. This particular facility is a long term user of various Belzona Systems and was aware of the longevity of Belzona repairs.

INDUSTRY

General Industry

LOCATION

Hospital in North Carolina, U.S.A.

APPLICATION DATE

July 1993

PRODUCTS

Belzona 4131 (Magma Screed)
Belzona 4411 (Granogrip)
Belzona 2211 (MP Hi-Build)

SUBSTRATE

Concrete

PHOTOS

1. Joint indentation evident through carpet
2. Concrete nosings spalled from traffic
3. Nosing rebuilt and joint sealed
4. Completed application ready for traffic

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

