

BELZONA REFURBISHES SCHOOL ROOF

ID: 2971



PROBLEM

Due to age and cracks in both the parapit walls and in the ashfelt the roof was leaking into the classrooms below.

APPLICATION SITUATION

Hall/Classroom roof on School

APPLICATION METHOD

Application was carried out in accordance with Belzona System Leaflet RPA-6 and RPA-10

BELZONA FACTS

School were so happy with the Belzona repair that they have now had another flat roof coated and some steps repaired with Belzona.

INDUSTRY

Buildings & Structures

LOCATION

Warwickshire, UK

APPLICATION DATE

September 2011

PRODUCTS

Belzona 3131 (WG Membrane)

Belzona 9361 (Reinforcing Sheet)

SUBSTRATE

Ashfelt

PHOTOS

1. and 2. Before Application

3. and 4. After Application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com



Copyright © 1952-2026 Belzona International Limited.