


HOSPITAL KITCHEN REPAIRED WITH BELZONA

ID: 298



PROBLEM

The metal expansion joint in the kitchen of this hospital had failed and the deterioration caused interruption in cart movement over the irregular sur-face.

APPLICATION SITUATION

Metal expansion joint or slip joint in hospital kitchen floor.

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflets FPA-5 and FPA-6.

BELZONA FACTS

The red Belzona® 4131 (Magma Screed) gives the repair area a close color match to the original quarry tile floor.

INDUSTRY

General Industry

LOCATION

Hospital in North Carolina, U.S.A.

APPLICATION DATE

Winter 2000

PRODUCTS

Belzona 4131 (Magma Screed)

Belzona 2211 (MP Hi-Build)

Belzona 4151 (Magma Quartz Resins)

SUBSTRATE

Quarry tile and concrete

PHOTOS

1. Damaged metal expansion joint
2. Finished application with Belzona 4151 recently applied
3. Nosing fully cured and ready for traffic

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com


BELZONA®

Copyright © 1952-2026 Belzona International Limited.