

BELZONA SEALS LEAKING CAUSTIC TANK

ID: 3007



PROBLEM

The caustic tank used as part of the process had sprung leaks along the weld seams.

APPLICATION SITUATION

Leaking caustic tank

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet TCC-1.

BELZONA FACTS

Re-welding the seams would have been costly, disruptive to production and ineffective. There wasn't sufficient budget to replace.

INDUSTRY

General Industry

LOCATION

Drinks Manufacturer, North London

APPLICATION DATE

November 2011

PRODUCTS

Belzona 1111 (Supermetal)

SUBSTRATE

Mild Steel

PHOTOS

1. Caustic leaking from weld seams
2. Surface preparation using MBX Bristle-blaster
3. First layer of Belzona 1111 being applied incorporating Reinforcement Tape
4. Finished application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

