

BELZONA REPAIRS DAMAGED CONCRETE IN PRIMARY SCHOOL PLAYGROUND

ID: 3032



PROBLEM

Some loose and damaged tiles had been removed in the playground bordering a class room. This had left concrete exposed and the area looking unsightly and representing a potential slip/trip issue for young children.

APPLICATION SITUATION

An area of damaged and exposed concrete within a Primary School external play area.

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet FPA-1

BELZONA FACTS

School required a quick and permanent solution to the issue. Traditional concrete/cement solutions were not appropriate as the bond strength would not be sufficient and it would be likely to shrink and crack creating additional problems. Hot work was out of the question and any products that would leave oily residue that could contaminate the children and their clothes were also not acceptable. Belzona® 4131 was chosen for its high bond strength, quick cure, high abrasion and impact resistance. Its ability to be feather edged ensured it was flush with adjacent areas to the repair. The work was completed in one day and to the complete satisfaction of the school who asked us to return to repair a similar problem in another area of the playground.

INDUSTRY

Buildings & Structures

LOCATION

Derbyshire UK

APPLICATION DATE

December 2009

PRODUCTS

Belzona 4131 (Magma Screed)

SUBSTRATE

Concrete / Cement

PHOTOS

1. The school play/activity area
2. The damaged area to be repaired
3. Belzona 4131 repair in progress
4. Completed application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com


BELZONA®