


# BELZONA SAVES SEVERAL WEEKS OF DOWNTIME

ID: 316



## PROBLEM

The rubber lined felt rolls are damaged from continuous abrasive wear of the wires edge and underside. This eventually causes sheet stretching and/or wrinkling.

## APPLICATION SITUATION

Rubber lined felt rolls.

## APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet SHM-9.

## BELZONA FACTS

Putting a new rubber cover on a roll is very expensive and the roll is usually out of service for weeks. The hardness of the Belzona repair must be close to the hardness of the rubber. In this case Belzona® 1111 (Super Metal) is 89 Shore D, or a P&J hardness between 8 and 9.

## INDUSTRY

Pulp & Paper

## LOCATION

Paper mill in Canada

## APPLICATION DATE

1996 and ongoing

## PRODUCTS

Belzona 1111 (Super Metal)

## SUBSTRATE

Rubber lined steel

## PHOTOS

1. Final rectification of Belzona repair
2. Felt roll back in service

For more examples of Belzona Know-How in Action, please visit [khia.belzona.com](http://khia.belzona.com)

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

[www.belzona.com](http://www.belzona.com)

