


BELZONA FOR EMERGENCY LEAK SEALING

ID: 323



PROBLEM

Leaking in the joint between a new, and existing tank. Loss of water estimated at one million gallons per month.

APPLICATION SITUATION

Wall of a filter/settling tank.

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet WPA-7.

BELZONA FACTS

This repair was carried out with a stream of water flowing out of the crack. Because of the anticipated movement in this joint, the repair was expected to be temporary. It did, in fact begin leaking some time later, but at a much reduced rate. When the tank is drained, a more permanent Belzona repair will be carried out.

INDUSTRY

Water / Wastewater

LOCATION

Water treatment plant in North Florida, U.S.A.

APPLICATION DATE

October 1992

PRODUCTS

Belzona 4211 (Magma Stop)
Belzona 4221 (Magma Seal)

SUBSTRATE

Concrete and reinforcing steel.

PHOTOS

1. Cleaning away old concrete
2. The completed repair

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

