

BELZONA REPAIRS A HOLE IN THIS HOPPER DREDGE HOSE

ID: 331



PROBLEM

A hole in the hose was caused from large volumes of abrasive solids passing through it.

APPLICATION SITUATION

Hopper dredge hose.

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet SOS-12.

BELZONA FACTS

Replacement cost of the hose is over \$10,000.

INDUSTRY

Marine

LOCATION

Dredge operators in California, USA

APPLICATION DATE

July 1998

PRODUCTS

Belzona 2111 (D&A Hi-Build)
Belzona 2311 (SR Elastomer)

SUBSTRATE

Fiber reinforced rubber

PHOTOS

1. View of the Dutch dredge ship
2. Hopper dredge hose being inspected
3. Extensive damage evident
4. Area being rebuilt with Belzona 2311 (SR Elastomer)

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

