


VACUUM PUMP RESTORED WITH BELZONA

ID: 3332



PROBLEM

Corrosive fumes had caused severe corrosion on all parts of this vacuum pump.

APPLICATION SITUATION

Liquid ring vacuum pump used in metal processing

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflets FBC-2, FBC-5 and FBC-10.

BELZONA FACTS

The Belzona has restored efficiency of the pump and will protect from future corrosion for many years.

INDUSTRY

General Industry

LOCATION

Sheet metal factory, Casablanca, Morocco

APPLICATION DATE

November 2011

PRODUCTS

Belzona 1321 (Ceramic S-Metal)

Belzona 1111 (Super Metal)

SUBSTRATE

Steel

PHOTOS

1. Original stator and end covers
2. Original rotor
3. Completed application on the stator
4. Completed application on the rotor

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

