

EXHAUST MIXER CORROSION PROBLEM SOLVED WITH BELZONA

ID: 336



PROBLEM

The original mixers suffered from corrosion from a combination of low concentrations of sulfuric acid and salt water. They needed to be replaced. The owner decided to coat his new mixers with Belzona® 1591 to prevent the situation from occurring again.

APPLICATION SITUATION

Corrosion of exhaust mixers.

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet VPF-2.

BELZONA FACTS

The application has been in service for three years and the owner is satisfied with the performance of Belzona.

INDUSTRY

Marine

LOCATION

Yacht in Florida, USA

APPLICATION DATE

August 1999

PRODUCTS

Belzona 1591

SUBSTRATE

Steel

PHOTOS

1. View of yacht
2. Exhaust Tru-hulls during surface preparation
3. Entire exhaust mixer grit blasted
4. Completed application with Belzona 1591

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com


BELZONA®

Copyright © 1952-2026 Belzona International Limited.