

BELZONA COATS PUMP BOWLS

ID: 34



PROBLEM

Corrosion damage to the housing; power plant wanted to increase the efficiency of the pump.

APPLICATION SITUATION

Two main cooling water pump bowls

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How Leaflets CEP-3 and CEP-10.

BELZONA FACTS

Belzona® 1341 (Supermetalgilde) was chosen for its efficiency enhancement properties in fluid flow systems.

INDUSTRY

Power

LOCATION

Power Plant in Mississippi

APPLICATION DATE

October 1995

PRODUCTS

Belzona 1341 (Supermetalgilde)

SUBSTRATE

Cast iron

PHOTOS

1. The impeller
2. Application of Belzona 1341 in progress
3. Two pump bowls coated

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

