

EMERGENCY REPAIR OF TYRE AT QUARRY WITH BELZONA

ID: 3426



PROBLEM

The tyre on the loader was damaged by sharp edged rock. Air was leaking when the crack was in bottom position under full load. Customer needed emergency repair so the loader could continue to operate until new tyres could be purchased and installed.

APPLICATION SITUATION

Tyre on heavy loader operating in quarry

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet SHM-9.

BELZONA FACTS

The alternative was to hire a subcontractor whilst the loader waited for new tyre to be obtained and fitted. Belzona repair stopped the air leakage and made possible for the loader to operate until new tyre arrived, for the total cost of only two hours of a hired loader!

INDUSTRY

Mining & Quarrying

LOCATION

Quarry, Croatia

APPLICATION DATE

May 2012.

PRODUCTS

Belzona 2311 (SR Elastomer)

SUBSTRATE

Rubber

PHOTOS

Damage in tyre 2 Damaged area prepared and conditioned with Belzona 2911 Embedding Belzona 9341 (Reinforcement Tape) into the crack
Repaired tyre ready to operate

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

