

BELZONA BOAT LIFT TIRE REPAIR

ID: 35



PROBLEM

Tires on lift are actually retreaded aircraft tires. Delamination of the tire tread due to use and exposure to the sun.

APPLICATION SITUATION

Drydock boat lift tire

APPLICATION METHOD

The application was carried out in accordance with a modified version of Belzona Know-How Leaflet SHM-9.

BELZONA FACTS

Tires cost approximately \$1,000 each. Two units of Belzona® 2311 (SR Elastomer) were used to repair the damaged area and to protect the tire from future deterioration. More importantly, it improved the reliability of the boat lift. If the machine is down, this company could be out of business.

INDUSTRY

Marine

LOCATION

Boat Repair Facility in Florida

APPLICATION DATE

February 1996

PRODUCTS

Belzona 2311 (SR Elastomer)

SUBSTRATE

Rubber

PHOTOS

1. View of boat lift used to hoist vessels from water
2. Tire tread is separating from the tire
3. Tire repaired with Belzona 2311

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

