

BELZONA PROTECTS FRACTIONATOR TOWER

ID: 359



PROBLEM

CUI (Corrosion Under Insulation) particularly around the support rings where moisture had accumulated.

APPLICATION SITUATION

Fractionator tower in cracker unit.

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet TCC-5. The insulation was removed from affected areas, substrate prepared and Belzona® 5851 (HA-Barrier) applied to the hot substrate.

BELZONA FACTS

Belzona® 5851 provides excellent corrosion protection to these badly cor-rod-ed areas without interruption to production.

INDUSTRY

Oil & Gas

LOCATION

Refinery in Singapore

APPLICATION DATE

April 2001

PRODUCTS

Belzona 5851 (HA-Barrier)

SUBSTRATE

Steel

PHOTOS

General view of the tower. The degree of corrosion clearly evident on the support rings. Application underway. Application complete.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

