

BELZONA TANK FARM

ID: 36



PROBLEM

Harsh chemicals attacking existing substrate which was installed in 1993.

APPLICATION SITUATION

Chemical containment area (5000 sq. ft.)

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How Leaflets TCC-9 and TCC-15.

BELZONA FACTS

The previous polymeric concrete repair material was damaged by chemical attack. The concrete was repaired and all areas protected.

INDUSTRY

Chemical & Petrochemical

LOCATION

Chemical Plant in South Alabama, USA

APPLICATION DATE

August 1995

PRODUCTS

Belzona 4131 (Magma Screed)
Belzona 4311 (Magma CR-1)

SUBSTRATE

Concrete and Polymeric Concrete

PHOTOS

1. View of damage to polymeric repair compound
2. Application of Belzona 4311 (Magma CR-1) in progress
3. 5000 sq. ft. area protected

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com



Copyright © 1952-2026 Belzona International Limited.