

CAR PARK REPAIRS WITH BELZONA

ID: 3619



PROBLEM

Carbonation of the reinforced concrete had led to extensive spalling on ceilings and walls, which required urgent repair.

APPLICATION SITUATION

Ceilings and walls in council car park

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet WPA-6.

BELZONA FACTS

The material's fast cure meant that the parking deck was reopened with minimum disruption and the repairs could be directly over-painted after just 3 days, which was the amount of time required to complete the concrete repair. The council selected Belzona as their first choice due to previous successful work undertaken for the council on another city car park.

INDUSTRY

Buildings & Structures

LOCATION

Local authority, Blackpool, England

APPLICATION DATE

October 2011

PRODUCTS

Belzona 4141 (Magma-Build)

SUBSTRATE

Reinforced concrete

PHOTOS

1 & 2. Severe spalling on ceilings

3 & 4. After: Belzona 4141 applied to the overhead surfaces

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

Copyright © 1952-2026 Belzona International Limited.

