

NEW BELZONA FLOOR SURFACE FOR WORKSHOP

ID: 364



PROBLEM

Previous floor coverings constantly failing and requiring regular maintenance. Floor cracked and generally in poor condition.

APPLICATION SITUATION

Floors in engineering workshop containing machine tools.

APPLICATION METHOD

Application was carried out in accordance with Belzona System Leaflet FPA-1

BELZONA FACTS

Belzona® 4131 provides a tough impact and oil resistant surface.

INDUSTRY

General Industry

LOCATION

Engineering company in Portugal

APPLICATION DATE

2002

PRODUCTS

Belzona 4131 (Magma-Screed)

SUBSTRATE

Concrete

PHOTOS

1. Belzona 4911 (Magma TX Conditioner) being applied to ensure maximum adhesion
2. Application of Belzona 4131 underway
3. Completed application
4. Another view of completed application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

