

BELZONA GRIP SYSTEM MAINTAINS BRAKE TEST EQUIPMENT

ID: 3644



PROBLEM

The drive rollers in the brake tester lose their grip and do not have sufficient friction with the tyre to complete an accurate test.

APPLICATION SITUATION

Equipment for testing brake efficiency on trucks.

APPLICATION METHOD

Application carried out in accordance with Belzona Know-How System Leaflet SHM-12.

BELZONA FACTS

The customer is happy about the result and the lifetime, which is approximately 4 years.

INDUSTRY

General Industry

LOCATION

Truck test centre, central Sweden

APPLICATION DATE

February 2012 (it has been done regularly since 2002)

PRODUCTS

Belzona 1321 (Ceramic S-Metal)

SUBSTRATE

Steel

PHOTOS

1. Worn rollers in the truck tester
2. Close-up of the worn roller
3. Roller coated with Grip system of Belzona 1321 and Silicon carbide aggregate, in the workshop
4. Finished application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

