


BELZONA PREVENTS GALVANIC AND CREVICE CORROSION ON RUDDER HORN

ID: 367



PROBLEM

Corrosion to internal of rudder horn had allowed the press fitted bronze bearing to become free. Bearing was approximately 908-mm (36-inch) diameter and 1050-mm (41-inch) long.

APPLICATION SITUATION

Corrosion to internal of rudder horn of 280,000 Ton VLCC (Very Large Crude Carrier) required re-fixing of bearing.

APPLICATION METHOD

The bearing was aligned and its position in the housing fixed using alignment bolts. The top and bottom of the housing were sealed using Belzona® 1211, then Belzona® 1321 was injected from below.

BELZONA FACTS

This method is used both in new-build and repair, and this example illustrates the ability to undertake this work while the vessel is afloat. Use of Belzona materials isolates and permanently fixes the bearing into position preventing galvanic and crevice corrosion.

INDUSTRY

Marine

LOCATION

Oil shipping company

APPLICATION DATE

1988

PRODUCTS

Belzona 1321 (Ceramic S-Metal)
Belzona 1211 (E-Metal)

SUBSTRATE

Carbon Steel and Bronze

PHOTOS

1. Belzona materials and team prepared for application.
2. Internal shot of bearing. Note arrows for injection ports.
3. Bearing after injection and prior to cleaning up of the Belzona 1211 seal.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

