

BELZONA EMERGENCY IN A COOLING TOWER

ID: 37



PROBLEM

Crack (leak) in the containment wall and floor.

APPLICATION SITUATION

Cooling tower containment

APPLICATION METHOD

The application was carried out in accordance with a modified version of Belzona Know-How Leaflet TCC-1.

BELZONA FACTS

The repair was performed overnight and the plant was operational early the next morning. It is estimated that the plant saved \$6,000 in water cost alone.

INDUSTRY

Power

LOCATION

Power Plant in Northwest Florida, USA

APPLICATION DATE

December 1996

PRODUCTS

Belzona 3121 (MR-7)

SUBSTRATE

Concrete

PHOTOS

1. The leak; sand bags used to hold back as much water as possible
2. The completed repair

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

