

BELZONA EXPANSION JOINTS: TOUGH ENOUGH FOR HEAVILY TRAVELLED HIGHWAYS

ID: 371



PROBLEM

The conventional expansion joints were too soft and could not withstand typical road debris. They were failing after less than one year.

APPLICATION SITUATION

Bridge expansion joints on Interstate 65.

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet FPA-6.

BELZONA FACTS

The failing conventional joints were also allowing solutions of calcium chloride and salt to seep through and damage the structural beams. The Belzona solution prevents this from occurring, and has performed perfectly since installation.

INDUSTRY

General Industry

LOCATION

Kentucky DOT (Department of Transportation) - U.S.A.

APPLICATION DATE

2002

PRODUCTS

Belzona 4521 (Magma-Flex Fluid)

SUBSTRATE

Steel

PHOTOS

1. The failed joint is easily removed thanks to poor adhesion
2. The surface for the new joint is prepared
3. Backer rod inserted
4. The application is complete and ready for vehicular traffic

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

