

BELZONA AIR HANDLING FAN & SHROUD

ID: 373



PROBLEM

Fan was constantly going out of balance due to particulate sticking to the blade.

APPLICATION SITUATION

Air Handling Fan

APPLICATION METHOD

The Application was carried out in accordance with Belzona Know-How System Leaflet FBC-2.

BELZONA FACTS

The fan was dynamically balanced before and after the application.

INDUSTRY

General Industry

LOCATION

Steel Company - Hamilton, Ontario - Canada

APPLICATION DATE

May 2003

PRODUCTS

Belzona 1341 (Supermetalgilde)

SUBSTRATE

Galvanized Steel

PHOTOS

1. Fan blasted to 3-4 mil profile, white metal finish
2. Second coat of Belzona 1341 completed on fan
3. Shroud coat completed

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

