

BELZONA TACKLES 98% SULFURIC ACID TANK

ID: 376



PROBLEM

Tank coating had failed, leading to severe pitting.

APPLICATION SITUATION

98% Sulfuric acid tank interior.

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How Systems leaflet TCC-5. After the tank was neutralized, it was blasted to a near white metal finish.

BELZONA FACTS

Application saved tens of thousands of dollars in downtime, as disassembly of machine takes four days. Four Months in service - PERFECT!

INDUSTRY

Power

LOCATION

Power Plant in Alabama - U.S.A.

APPLICATION DATE

February 2003

PRODUCTS

Belzona 1111 (Super Metal)
Belzona 4311 (Magma CR-1)

SUBSTRATE

Steel

PHOTOS

1. & 2. Before

3. & 4. After

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

