

BELZONA REPAIRS AND PROTECTS AUTO REPAIR SHOP FLOOR

ID: 377



PROBLEM

Floor area damaged due to exposure to sulfuric acid.

APPLICATION SITUATION

Parts & Battery Storage Area

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflets FPA-1 and TCC-15.

BELZONA FACTS

The facility is over 30 years old and the customer had made several attempts to repair the floor. In each case, they used some type of concrete repair products to make the repair and coat with several types of paint. Each method was more expensive than the Belzona repair and none were effective.

INDUSTRY

General Industry

LOCATION

Auto Repair Center in Northern Florida - U.S.A.

APPLICATION DATE

May 2003

PRODUCTS

Belzona 4131 (Magma-Screed)
Belzona 5811 (Immersion Grade)

SUBSTRATE

Concrete

PHOTOS

1. Prior to application
2. Prepared floor
3. Belzona 4131 (Magma-Screed) and Belzona 5811 (Immersion-Grade) applied to protect application area long term

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

