

# BELZONA PROTECTION TO BUTANE TANK BASE

ID: 379



## PROBLEM

Corrosion at base of tank. At same time, timber supports were being renewed.

## APPLICATION SITUATION

Insulated tank containing Butane at -6°C (21°F).

## APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet GSS-3.

## BELZONA FACTS

Belzona application creates a flexible, waterproof but microporous seal at junction of tank and base to provide long-term corrosion protection.

## INDUSTRY

Chemical & Petrochemical

## LOCATION

International Petroleum Company - Australia

## APPLICATION DATE

2002

## PRODUCTS

Belzona 3211 (Lagseal)

## SUBSTRATE

Steel, Concrete and Timber

## PHOTOS

1. General view of the tank
2. Preparation of tank and base underway. Tank jacked up ready to install new timbers
3. Application underway
4. Application being completed

For more examples of Belzona Know-How in Action, please visit [khia.belzona.com](http://khia.belzona.com)

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

[www.belzona.com](http://www.belzona.com)

