

BELZONA UPGRADES HOSPITAL ROOF

ID: 3866



PROBLEM

This hospital roof required an insulation upgrade and in addition, weatherproofing to prevent any further damage.

APPLICATION SITUATION

Large hospital roof which had deteriorated through weathering

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet RPA-8. After installing insulation boards overlayed with felt, a fully reinforced Belzona® 3111 system was applied.

BELZONA FACTS

Since the application, the customer has saved on both heating and air conditioning costs and in addition, has reduced their carbon footprint.

INDUSTRY

Buildings & Structures

LOCATION

Hospital, UK

APPLICATION DATE

April 2011

PRODUCTS

Belzona 3111 (Flexible Membrane)

SUBSTRATE

New base layer Felt

PHOTOS

1. Insulation boards ready for installation on the deteriorated roof
2. First coat of Belzona 3111 applied
3. Completed application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

