

BELZONA SAFETY GRIP SYSTEM ON STAIRS

ID: 3879



PROBLEM

A potential slip hazard was identified on the metal stairs.

APPLICATION SITUATION

Metal stairs leading to a mezanine floor area.

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet FPA-8. After preparing the area with an MBX Bristle Blaster stripes of Belzona® 4411 red and yellow safety colours incorporating Belzona® 9221 aggregate were applied.

BELZONA FACTS

Belzona® 4411 gave a quick and easy solution to removing a slip hazard from a busy set of stairs. The non-slip properties of the Belzona Grip system are ideal for this dusty environment and safety colours aide in both identifying the step edges and in highlighting the potential hazard.

INDUSTRY

General Industry

LOCATION

Manufacturer, UK

APPLICATION DATE

July 2012

PRODUCTS

Belzona 4411 (Granogrip)

SUBSTRATE

Steel

PHOTOS

1. Steps before Belzona Application
2. Abraded and Masked steps
3. Half of steps completed
4. Completed application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

