

REFURBISHMENT OF LARGE DIFFUSER PUMPS WITH BELZONA

ID: 3887



PROBLEM

The pumps, each weighing over eleven tonnes without the motor, were failing to deliver sufficient flow to satisfy customer demand.

APPLICATION SITUATION

Two 48" cooling water circulating pumps

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflets CEP-1, 3, 4 & 5.

BELZONA FACTS

After refurbishment, the pumps were returned to the power station, where they were installed, aligned and commissioned. Both pumps were returned to service within an eight week period and within budget. The customer has expressed his great satisfaction with the service provided and is already reaping the benefits of the newly coated pumps.

INDUSTRY

Power

LOCATION

Power station, Northern Ireland

APPLICATION DATE

2010

PRODUCTS

Belzona 1111 (Super Metal)
Belzona 1311 (Ceramic R-Metal)
Belzona 1341 (Supermetalgilde)
Belzona 5811 (Immersion Grade)

SUBSTRATE

Cast iron

PHOTOS

1. One of the diffuser pumps after disassembly
2. Degree of damage clearly evident on the diffuser vanes
3. Coated diffuser vanes
4. Coating of the pump internals and bell mouth with Belzona 1341 and Belzona 5811 externally

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com


BELZONA

Copyright © 1952-2026 Belzona International Limited.