

BELZONA IS FOR ROOF PROBLEM AREAS

ID: 389



PROBLEM

Heat, UV light, and pollution from the foundry below created water leaks on the roof mending joints, seams, standing water areas and flashings.

APPLICATION SITUATION

Roof

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflets RPA-1, RPA-6 and RPA-8.

BELZONA FACTS

The Belzona System was used to seal all leaks. After several years there are no leaks and the system is in perfect condition.

INDUSTRY

General Industry

LOCATION

Manufacturer of fine decorative metal art work in Santa Fe, New Mexico U.S.A.

APPLICATION DATE

December 2001

PRODUCTS

Belzona 3111 (Flexible Membrane)

SUBSTRATE

Metal and built up roof

PHOTOS

1. View of the roof.
2. Flashing being sealed with the system.
3. Vertical seams are sealed.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

