



SLOPED SURFACE MADE SAFE WITH BELZONA

ID: 390



PROBLEM

Sloped walkway with exposed aggregate became very slippery when wet, creating a safety hazard.

APPLICATION SITUATION

Walkway entrance to office building.

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet FPA-8.

BELZONA FACTS

The non-slip system remains in perfect condition after several years. The potential for slippage is alleviated.

INDUSTRY

General Industry

LOCATION

Commercial Business Park in Albuquerque, New Mexico U.S.A.

APPLICATION DATE

September 2001

PRODUCTS

Belzona 4411 (Granogrip)

SUBSTRATE

Concrete with exposed aggregate

PHOTOS

1. The slope walkway entrance was very slippery when wet.
2. The pattern is created as tape is being laid.
3. Application of the Belzona Non-Slip System in progress.
4. The finished non-slip system; the pedestrian area is made safe.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

