


BELZONA UPGRADES SAFETY AND APPEARANCE OF SCHOOL ENTRANCE

ID: 3973



PROBLEM

Step nosings had become damaged and overall very dirty. The school wanted the main entrance upgrading and wanted to ensure the steps were safe for its staff, pupils and visitors.

APPLICATION SITUATION

Steps leading to school main entrance

APPLICATION METHOD

Application was carried out in accordance with Belzona System Leaflets FPA-1 and FPA-8. The concrete step nosings were repaired using Belzona® 4111 before coating with Belzona® 5231. Finally a Belzona® 4411 grip system was applied to step nosings.

BELZONA FACTS

The application was completed by Belzona to a very high standard which was confirmed by the client. Not only has appearance been upgraded but the high visibility, non slip system on the step nosings provides improved safety by reducing risk of falls.

INDUSTRY

General Industry

LOCATION

Secondary School, Port Talbot, South Wales

APPLICATION DATE

May 2012

PRODUCTS

Belzona 4111 (Magma Quartz)
Belzona 5231 (SG Laminate)
Belzona 4411 (Granogrip)

SUBSTRATE

Concrete

PHOTOS

1. Deteriorating steps at the entrance to the school
2. Repair to steps using Belzona 4111
3. Application of Belzona 5231 overall
4. Complete repair with Belzona 4411 grip system applied to the step nosings.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

